

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,991,313 B2
DATED : January 31, 2006
INVENTOR(S) : Masahiko Sasa

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Title page.

Item [56], **References Cited, U.S. PATENT DOCUMENTS**, should read as follows:

-- 4,510,510A	4/1985	Terasawa
4,558,326 A *	12/1985	Kimura et al.
5,557,306 A *	9/1996	Fukushima et al.
6,145,802	11/2000	Nakagaki et al.
		248/638 --.

FOREIGN PATENT DOCUMENTS, should read as follows:

-- CN	1136501 A	11/1996
JP	404070355 A *	3/1992
JP	404080037 A *	3/1992
JP	B2 2703647	10/1997
JP	A 10-138506	5/1998
JP	A 2000-065127	3/2000
JP	A 10-305594	11/1998
JP	A 10-114085	5/1998
JP	A 03-099857	4/1991 --.

Column 11,

Line 10, claim 5 should read as follows:

5. The ink jet printer according to claim 2, wherein an orifice for exhausting part of the pressurized air is provided in a vicinity of an opposite end of the air supply tube to the air pump.

Signed and Sealed this

Eighteenth Day of April, 2006



JON W. DUDAS
Director of the United States Patent and Trademark Office